

M8x40 - 1ks
 M8x25 - 6ks
 M10x30 - 4ks
 M12x110 - 4ks
 M12x70 - 2ks (A,I)
 M12x90 - 2ks (I)
 M12x19 - 4ks (C)



SM8 - 1ks



M10 - 4ks
 M12 - 6ks (A, I)
 M12 - 4ks (C)



P9 - 6ks



P8 - 1ks




PP8 - 6ks
 PP10 - 4ks
 PP12 - 6ks (A, I)
 PP12 - 8ks (C)






PR14 - 1ks

C



M12x19 - 4ks

DETAIL



M12x90 - 2ks

