

M10x35 - 8ks  
 M12x35 - 4ks  
 M12x70 - 3ks (A)  
 M12x90 - 1ks (C)  
 M12x19 - 4ks (C)



M12 - 7ks (A)  
 M12 - 5ks (C)



P12 - 2ks (A)  
 P12 - 3ks (C)




PP10 - 8ks  
 PP12 - 7 ks (A)  
 PP12 - 9 ks (C)



2ks (A)  
 4ks (C)

C



DETAIL

