

M8x40 - 1ks
 M10x40 - 4ks
 M12x30 - 4ks
 M12x70 - 2ks (A)
 M12x90 - 2ks (I)
 M12x19 - 4ks (C)



MS8 - 1ks



M12 - 6ks (A, I)
 M12 - 4ks (C)



P8 - 1ks

PP10 - 4ks
 PP12 - 6ks (A, I)
 PP12 - 8ks (C)



D25x5 - 2ks




D30x8 - 2ks






PR14 - 1ks


C



M12x19 - 4ks



M12x90 - 2ks



I

IC 400 12 3

SUZUKI SX4, SUZUKI SX4 S-CROSS
 Kód: S1075(A,I,C) - 16. 10. 2013

A